


## ATTENTION:

If the pulley is removed, torque the (9) 1/4-20 X 3/4 bolts to 120 in/lbs. (10 ft/lbs.) at re-assembly.



Please contact Customer Tech at Horschel Motorsports-Fluidampr 716-592-1000  
([www.fluidampr.com](http://www.fluidampr.com)) for any comments, suggestions or questions.